

Under Review Notification

Raised By: Victoria Seib

Product #: D212-803

Date: 15.05.21

Product Name: LH PIC

Part Number (D-Part and 9-Digit)	Drawing/Document & Current Affected Revision	"Y" or "N" Required for Each Part							Reserved ECN Log Number	Instructions Relevant to Each Part
		HOLD SHIPMENT	Red Tag/Quarantine Stock	Advise Customers	Stop Production	Re-Work Stock	IPP Under Review	Product Specifications Under Review		
D5155-041	D5155 Rev. A	N	N	N	Y	Y	N	Y	15-577	Manufacture per D5155-PBX
D5155-043	D5155 Rev. A	N	N	N	Y	Y	N	Y	15-577	Manufacture per D5155-PBX
D5155-045	D5155 Rev. A	N	N	N	Y	Y	N	Y	15-577	Manufacture per D5155-PBX
D5155-047	D5155 Rev. A	N	N	N	Y	Y	N	Y	15-577	Manufacture per D5155-PBX
D5155-1	D5155 Rev. A	N	N	N	Y	Y	N	Y	15-577	Manufacture per D5155-PBX
D5155-3	D5155 Rev. A	N	N	N	Y	Y	N	Y	15-577	Manufacture per D5155-PBX
D5155-5	D5155 Rev. A	N	N	N	Y	Y	N	Y	15-577	Manufacture per D5155-PBX
D5155-7	D5155 Rev. A	N	N	N	Y	Y	N	Y	15-577	Manufacture per D5155-PBX
D5156-7	D5156 Rev. A	N	N	N	Y	Y	N	Y	15-577	Manufacture per D5156-PBX
D5046-041	D5046 Rev. A	N	N	N	Y	Y	N	Y	15-577	Manufacture per D5046-PBX
D5046-043	D5046 Rev. A	N	N	N	Y	Y	N	Y	15-577	Manufacture per D5046-PBX
D5046-045	D5046 Rev. A	N	N	N	Y	Y	N	Y	15-577	Manufacture per D5046-PBX

Description of Issue:

- Terminal block mounting hole interferes with conduit weld, per NCR 15-4989 on D5155 parts
- Parts may still be manufactured per preliminary drawing D5155 Rev. B, D5156 Rev B, D5046 Rev. B and D4410 Rev. E
- Add necessary revisions to D5046 drawing to be consistent with D5155 and CAR 14-92

Distribution:

VP Operations

Chief Engineer

Production Engineers

Director of Operations

Engineering Project Managers

Planning Manager

Director Quality Assurance

Engineering Clerk

Program Manager

Director of Engineering

Customer Support Manager

Under Review Notification

Raised By: Victoria Seib

Product #: D212-803

Date: 15.05.21

Product Name: LH PIC

Part Number (D-Part and 9-Digit)	Drawing/Document & Current Affected Revision	"Y" or "N" Required for Each Part							Reserved ECN Log Number	Instructions Relevant to Each Part
		HOLD SHIPMENT	Red Tag/Quarantine Stock	Advise Customers	Stop Production	Re-Work Stock	IPP Under Review	Product Specifications Under Review		
D5046-045	D5046 Rev. A	N	N	N	Y	Y	N	Y	15-577	Manufacture per D5046-PBX
D5046-1	D5046 Rev. A	N	N	N	Y	Y	N	Y	15-577	Manufacture per D5046-PBX
D5046-3	D5046 Rev. A	N	N	N	Y	Y	N	Y	15-577	Manufacture per D5046-PBX
D5046-5	D5046 Rev. A	N	N	N	Y	Y	N	Y	15-577	Manufacture per D5046-PBX
D5046-7	D5046 Rev. A	N	N	N	Y	Y	N	Y	15-577	Manufacture per D5046-PBX
D4410-5	D4410 Rev. D	N	N	N	Y	Y	N	Y	15-577	Manufacture per D4410-PEX

Description of Issue:

- Parts may still be manufactured per preliminary drawing D5046 Rev. B, D4410 Rev. E
- Add necessary revisions to D5046 drawing to be consistent with D5155 and CAR 14-92
- Key hole in wrong location on D4410-5 per CAR 14-92

Distribution:

VP Operations

Director of Operations

Director Quality Assurance

Director of Engineering

Chief Engineer

Engineering Project Managers

Engineering Clerk

Customer Support Manager

Production Engineers

Planning Manager

Program Manager